



- Install New Manhole (10)
- Install Inside Drop (0)
- Cementitous Coating (3)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (1)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (1)

→ Mainline Relay (58)








SARP10 Rehabilitation Project **Group 3 Relay**

Overview


Manhole (No Rehab) Gravity Main (No Rehab)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (1)








SARP10 Rehabilitation Project **Group 3 Relay** Grid A2

Page 1 of 54

Manhole (No Rehab)

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)



Note: Recorded manhole rim to invert measurements are indicated below the Facility ID. Point Repair locations are approximate. Maps have some some overlap with other map pages.

Structurally Replace Manhole (0)


Current Grid: A6


Gravity Main (Rehab By Others)

Gravity Main (No Rehab)

Grid A6


Page 2 of 54





Install New Manhole (0)

- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (1)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)






BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay Grid B3**

Gravity Main (Rehab By Others) Page 3 of 54

Manhole (Rehab By Others)

Manhole (No Rehab)




Note: Recorded manhole rim to invert measurements are indicated below the Facility ID. Point Repair locations are approximate. Maps have some some overlap with other map pages.


Page 4 of 54

Gravity Main (No Rehab)

Structurally Replace Manhole (0)

Current Grid: B4









- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)


Pipe Rehab → Mainline Relay (1)

Manhole (Rehab By Others)

Gravity Main (Rehab By Others)

Manhole (No Rehab)

Gravity Main (No Rehab)








BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay** Grid C4 Page 7 of 54





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)







BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay** Grid C5 Page 8 of 54

Gravity Main (Rehab By Others) Gravity Main (No Rehab)


Manhole (Rehab By Others)

Manhole (No Rehab)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)










Group 3 Relay Grid C6


Page 9 of 54

Manhole (No Rehab)

Gravity Main (Rehab By Others) Gravity Main (No Rehab)


Manhole (Rehab By Others)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (1)







SARP10 Rehabilitation Project


Group 3 Relay Grid E5


Page 10 of 54

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)


Manhole (No Rehab)





- Install New Manhole (1)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (2)







BLACK & VEATCH
Building a world of difference.


SARP10 Rehabilitation Project **Group 3 Relay** Grid F3

Page 11 of 54

Manhole (No Rehab)


Gravity Main (Rehab By Others) Gravity Main (No Rehab)


Manhole (Rehab By Others)





- Install New Manhole (2)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)







BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay** Grid F4


Page 12 of 54


Manhole (No Rehab)

Gravity Main (Rehab By Others) Gravity Main (No Rehab)


Manhole (Rehab By Others)

Current Grid: F4





- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)



BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay Grid G5**


Page 13 of 54

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)


Manhole (No Rehab)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (1)








SARP10 Rehabilitation Project **Group 3 Relay** Grid H4

Page 14 of 54

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)

Manhole (No Rehab)





- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

SARP10 Rehabilitation Project Group 3 Relay Grid H5


Page 15 of 54


 \rightarrow

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)

Manhole (No Rehab)






Install New Manhole (0)

- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (2)








SARP10 Rehabilitation Project **Group 3 Relay**

Grid I1

Page 16 of 54

Manhole (No Rehab) Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)





- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)




SARP10 Rehabilitation Project **Group 3 Relay Grid I5**


Page 17 of 54


Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (No Rehab)

Manhole (Rehab By Others)







Install New Manhole (0)

- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)


Pipe Rehab → Mainline Relay (1)

Manhole (Rehab By Others)

Gravity Main (Rehab By Others)

Manhole (No Rehab)

Gravity Main (No Rehab)








BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay** Grid J6 Page 19 of 54





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (2)







BLACK & VEATCH
Building a world of difference.


SARP10 Rehabilitation Project **Group 3 Relay Grid J8**

Page 20 of 54

Manhole (No Rehab)

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)






Install New Manhole (2)

- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)

Structurally Replace Manhole (0)








SARP10 Rehabilitation Project **Group 3 Relay** Grid J9

Page 21 of 54

Manhole (Rehab By Others) Manhole (No Rehab) Gravity Main (Rehab By Others) Gravity Main (No Rehab)





Install New Manhole (1)


- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)

Pipe Rehab → Mainline Relay (2)

Manhole (Rehab By Others)

Gravity Main (Rehab By Others)

Manhole (No Rehab)








BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay** Grid J10 Page 22 of 54

Structurally Replace Manhole (0)

Gravity Main (No Rehab)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (1)







SARP10 Rehabilitation Project **Group 3 Relay** Grid J12


Page 23 of 54

Manhole (No Rehab) Gravity Main (Rehab By Others)

Gravity Main (No Rehab)

Manhole (Rehab By Others)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (1)










SARP10 Rehabilitation Project **Group 3 Relay** Grid J13 Page 24 of 54


Manhole (No Rehab)

Gravity Main (Rehab By Others)

Gravity Main (No Rehab)

Manhole (Rehab By Others)











SARP10 Rehabilitation Project **Group 3 Relay** Grid L3


Page 26 of 54












- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)







SARP10 Rehabilitation Project **Group 3 Relay** Grid M1

Page 30 of 54

Manhole (No Rehab) Gravity Main (Rehab By Others) Gravity Main (No Rehab)


Manhole (Rehab By Others)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (1)








SARP10 Rehabilitation Project **Group 3 Relay** Grid M4

Page 31 of 54

Manhole (No Rehab)

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)




Manhole (Rehab By Others)

Gravity Main (Rehab By Others)

Manhole (No Rehab)

Gravity Main (No Rehab)










BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay Grid M8** Page 32 of 54

Structurally Replace Manhole (0)










- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)






SARP10 Rehabilitation Project **Group 3 Relay** Grid M11


Page 35 of 54

Gravity Main (Rehab By Others) Gravity Main (No Rehab)


Manhole (Rehab By Others)

Manhole (No Rehab)





- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)




SARP10 Rehabilitation Project **Group 3 Relay** Grid M12

Page 36 of 54


Manhole (No Rehab) Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)





- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)








BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay Grid N8** Page 37 of 54

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (No Rehab)


Manhole (Rehab By Others)







- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0) Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)



SARP10 Rehabilitation Project **Group 3 Relay** Grid N12

Page 39 of 54

Manhole (No Rehab) Gravity Main (Rehab By Others) Gravity Main (No Rehab)


Manhole (Rehab By Others)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (2)







SARP10 Rehabilitation Project **Group 3 Relay** Grid O8


Page 40 of 54

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (No Rehab)

Manhole (Rehab By Others)






- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)

Manhole (Rehab By Others)

Manhole (No Rehab)

Gravity Main (No Rehab)


Gravity Main (Rehab By Others)







SARP10 Rehabilitation Project **Group 3 Relay Grid O9**

Page 41 of 54










- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (1)







SARP10 Rehabilitation Project **Group 3 Relay** Grid P10


Page 44 of 54

Gravity Main (Rehab By Others)

Gravity Main (No Rehab)

Manhole (No Rehab)

Manhole (Rehab By Others)





- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

SARP10 Rehabilitation Project Group 3 Relay Grid P11

Page 45 of 54


→

Gravity Main (Rehab By Others)Gravity Main (No Rehab)

Manhole (Rehab By Others)


Manhole (No Rehab)






- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)









SARP10 Rehabilitation Project **Group 3 Relay** Grid Q10


Page 46 of 54

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (No Rehab)


Manhole (Rehab By Others)





- Install New Manhole (0)
- Install Inside Drop (0)
- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

Pipe Rehab → Mainline Relay (1)







BLACK & VEATCH
Building a world of difference.


SARP10 Rehabilitation Project **Group 3 Relay** Grid R10 Page 47 of 54

Gravity Main (Rehab By Others)

Gravity Main (No Rehab)

Manhole (No Rehab)

Manhole (Rehab By Others)



Gravity Main (No Rehab) Note: Recorded manhole rim to invert measurements are indicated below the Facility ID. Point Repair locations are approximate. Maps have some some overlap with other map pages.

Structurally Replace Manhole (0)

Gravity Main (Rehab By Others)

Grid S9

Page 48 of 54

Central Ave

Current Grid: S9





- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)


SARP10 Rehabilitation Project **Group 3 Relay Grid T8**

Page 49 of 54


Manhole (No Rehab)

Gravity Main (Rehab By Others) Gravity Main (No Rehab)


Manhole (Rehab By Others)







- Install Inside Drop (0)
- Cementitous Coating (2)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)







BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay Grid U8** Page 51 of 54


Note: Recorded manhole rim to invert measurements are indicated below the Facility ID. Point Repair locations are approximate. Maps have some some overlap with other map pages.

Manhole (Rehab By Others)

Gravity Main (Rehab By Others)


Manhole (No Rehab)

Gravity Main (No Rehab)





- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)



BLACK & VEATCH
Building a world of difference.

SARP10 Rehabilitation Project **Group 3 Relay** Grid U10

Page 52 of 54

Manhole (No Rehab)


Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)





- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)



SARP10 Rehabilitation Project **Group 3 Relay**

Grid V9

Page 53 of 54

Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (No Rehab)

Manhole (Rehab By Others)





- Cementitous Coating (0)
- Repair Bench/Channel (0)
- △ Cementitous Coating and Install Inside Drop (0)
- ▲ Cementitous Coating and Repair Bench/Channel (0)
- Repair Bench/Channel and Install Inside Drop (0)
- Structurally Replace Manhole (0)

SARP10 Rehabilitation Project **Group 3 Relay** Grid V10

Page 54 of 54

Manhole (No Rehab) Gravity Main (Rehab By Others) Gravity Main (No Rehab)

Manhole (Rehab By Others)